



Photograph No.: 1

Date: 1/18/13

Location: Intersection of Elm Avenue and Veneer Road

Direction of View: North

Description of View: Intersection of Elm Avenue and Veneer Road (Pre-construction)



Photograph No.: 2

Date: 1/18/13

Location: Intersection of Elm Avenue and Veneer Road

Direction of View: West

Description of View: Intersection of Elm Avenue and Veneer Road (Pre-construction)

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 1 & 2
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 3

Date: 1/18/13

Location: Atlantic Metrocast Inc. (AMI) service road (Pre-construction)

Direction of View: West

Description of View: Used as a temporary bypass road during utility relocation work



Photograph No.: 4

Date: 1/18/13

Location: Underneath Jordan Bridge (FIGG Property)

Direction of View: East

Description of View: Site view looking to the East (Pre-construction)

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 3 & 4
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 5

Date: 1/18/13

Location: Atlantic Wood Industries (AWI) project site

Direction of View: East

Description of View: Project site looking to the East (Pre-construction)



Photograph No.: 6

Date: 1/18/13

Location: AWI project site

Direction of View: West

Description of View: Site view looking to the West (Pre-construction)

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 5 & 6
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 7

Date: 1/18/13

Location: AWI project site

Direction of View: Northwest

Description of View: Project site looking to the Northwest (Pre-construction)



Photograph No.: 8

Date: 1/18/13

Location: AWI project site

Direction of View: West


Description of View: Project site looking to the West (Pre-construction)

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 7 & 8
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07




Photograph No.: 9

Date: 1/25/13

Location: JB-1

Direction of View: Southwest

Description of View: Well point installation activities



Photograph No.: 10

Date: 1/30/13

Location: North of JB-1

Direction of View: Northwest

Description of View: Well point installation activities

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 9 & 10
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 11

Date: 1/29/13

Location: North of JB-1

Direction of View: Northwest

Description of View: Installation of header piping for de-watering system



Photograph No.: 12

Date: 2/19/13

Location: Between JB-1 and JB-2

Direction of View: North

Description of View: Well point de-watering system

WRSScompass Project No. 33-74-120000




WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 11 & 12
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 13
Date: 2/21/13
Location: JB-1
Direction of View: North
Description of View: Excavating footprint of JB-1



Photograph No.: 14
Date: 3/15/13
Location: JB-1
Direction of View: North
Description of View: Excavating footprint of JB-1

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 13 & 14
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 15

Date: 3/14/13

Location: JB-1

Direction of View: East

Description of View: Rip rap material applied for sub-base stabilization at JB-1



Photograph No.: 16

Date: 3/14/13

Location: JB-1

Direction of View: West

Description of View: Select bedding material (No. 57 stone) applied to bottom of JB-1

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 15 & 16
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 17
Date: 3/15/13
Location: JB-1
Direction of View: Northwest
Description of View: Compacting base of JB-1



Photograph No.: 18
Date: 3/19/13
Location: JB-1
Direction of View: East
Description of View: Forming foundation of JB-1

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 17 & 18
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 19
Date: 3/19/13
Location: JB-1
Direction of View: South
Description of View: Forming rebar for foundation of JB-1



Photograph No.: 20
Date: 3/25/13
Location: JB-1
Direction of View: South
Description of View: Pouring concrete foundation of JB-1

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 19 & 20
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 21
Date: 3/25/13
Location: JB-1
Direction of View: East
Description of View: Concrete foundation of JB-1



Photograph No.: 22
Date: 4/2/13
Location: JB-1
Direction of View: Southeast
Description of View: Forming walls of JB-1

WRSSCOMPASS Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 21 & 22
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 23

Date: 4/3/13

Location: JB-1

Direction of View: Southwest

Description of View: Utilizing crane to position 42-inch diameter steel pipe for connection



Photograph No.: 24

Date: 4/3/13

Location: JB-1

Direction of View: Southwest

Description of View: Connecting (1 of 3) 42-inch diameter steel pipes north of concrete deadman

WRScompass Project No. 33-74-120000




WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 23 & 24
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 25
Date: 4/13/13
Location: JB-1
Direction of View: West
Description of View: Forming walls of JB-1



Photograph No.: 26
Date: 4/18/13
Location: JB-1
Direction of View: Southeast
Description of View: Pouring concrete walls of JB-1

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 25 & 26
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 27

Date: 4/23/13

Location: JB-1

Direction of View: Southeast

Description of View: View of trench drains at JB-1



Photograph No.: 28

Date: 4/24/13

Location: JB-1

Direction of View: East

Description of View: View of triple 42-inch diameter steel pipes installed

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 27 & 28
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 29

Date: 4/25/13

Location: North of JB-1

Direction of View: Southeast

Description of View: View of triple 36-inch diameter RCP installation activities



Photograph No.: 30

Date: 4/27/13

Location: North of JB-1

Direction of View: Southeast

Description of View: View of backfilling/compacting efforts in pipe trench

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 29 & 30
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 31

Date: 4/1/13

Location: JB-1

Direction of View: Southeast

Description of View: View of liner installation activities around JB-1



Photograph No.: 32

Date: 5/4/13

Location: JB-1

Direction of View: East

Description of View: View of baton strips and liner installation activities around JB-1

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 31 & 32
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 33

Date: 5/4/13

Location: South of JB-1

Direction of View: North

Description of View: View of pipe boots around the triple 42-inch diameter steel pipes



Photograph No.: 34

Date: 6/6/13

Location: Inside JB-1

Direction of View: Southeast

Description of View: View of tide flex valve (1 of 3) installed on the south wall of JB-1

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 33 & 34
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 35
Date: 9/11/13
Location: Inside JB-1
Direction of View: South
Description of View: View of installed trash grate (1 of 3)



Photograph No.: 36
Date: 10/2/13
Location: JB-1
Direction of View: South
Description of View: View of monitoring port location north of JB-1 (1 of 2)

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 35 & 36
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 37

Date: 3/18/13

Location: JB-1 to JB-2

Direction of View: North

Description of View: Excavating and sloping sidewalls of pipe trench



Photograph No.: 38

Date: 3/20/13

Location: JB-1 to JB-2

Direction of View: South

Description of View: View of contaminated material being loaded out and transported to Stockpile-A

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 37 & 38
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 39

Date: 4/9/13

Location: JB-1 to JB-2

Direction of View: North

Description of View: View of miscellaneous debris uncovered during excavation activities.



Photograph No.: 40

Date: 4/9/13

Location: JB-1 to JB-2

Direction of View: Northwest


Description of View: View of air monitoring/sampling station

WRScompass Project No. 33-74-120000




WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 39 & 40
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 41
Date: 3/28/13
Location: JB-1 to JB-2
Direction of View: South
Description of View: View of textured, 60 mil., HDPE trench liner



Photograph No.: 42
Date: 3/29/13
Location: JB-1 to JB-2
Direction of View: East
Description of View: View of welded liner seam

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 41 & 42
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 43

Date: 5/7/13

Location: JB-1 to JB-2

Direction of View: South

Description of View: View of select bedding material (No. 57 stone) applied to bottom of pipe trench



Photograph No.: 44

Date: 5/13/13

Location: JB-1 to JB-2

Direction of View: Southeast

Description of View: View of 36-inch RCP installation activities

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 43 & 44
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07




Photograph No.: 45

Date: 5/14/13

Location: JB-1 to JB-2

Direction of View: Southeast

Description of View: Backfilling activities inside pipe trench with select fill material



Photograph No.: 46

Date: 5/16/13

Location: JB-1 to JB-2

Direction of View: Southeast

Description of View: View of compaction efforts inside pipe trench

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 45 & 46
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 47

Date: 3/27/13

Location: JB-1 to JB-2

Direction of View: South

Description of View: View of anchor trench on the top of the east wall



Photograph No.: 48

Date: 4/16/13

Location: JB-2

Direction of View: North

Description of View: Excavating footprint of JB-2

WRScompass Project No. 33-74-120000




WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 47 & 48
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 49
Date: 4/15/13
Location: JB-2
Direction of View: West
Description of View: Excavating footprint of JB-2



Photograph No.: 50
Date: 4/15/13
Location: JB-2
Direction of View: Northwest
Description of View: View of contaminated material being loaded out and transported to Stockpile-A

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 49 & 50
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 51

Date: 5/30/13

Location: JB-2

Direction of View: North

Description of View: View of existing asbestos lined storm drain pipe removal



Photograph No.: 52

Date: 5/7/13

Location: JB-2

Direction of View: Northeast

Description of View: Forming foundation of JB-2

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 51 & 52
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 53
Date: 5/15/13
Location: JB-2
Direction of View: West
Description of View: Forming walls of JB-2



Photograph No.: 54
Date: 6/4/13
Location: JB-2
Direction of View: North
Description of View: View of concrete walls and foundation of JB-2

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 53 & 54
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 55

Date: 5/9/13

Location: JB-2

Direction of View: N/A

Description of View: Concrete testing performed by McCallum Testing Laboratories, Inc.



Photograph No.: 56

Date: 6/5/13

Location: JB-2 to JB-3

Direction of View: West

Description of View: Pipe trench between JB-2 and JB-3

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 55 & 56
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 57
Date: 10/21/13
Location: JB-2 to JB-3
Direction of View: South
Description of View: Installation of dual 36-inch diameter RCP



Photograph No.: 58
Date: 10/21/13
Location: JB-2 to JB-3
Direction of View: West
Description of View: Installation of dual 36-inch diameter RCP

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 57 & 58
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 59

Date: 8/20/13

Location: JB-2 to JB-3

Direction of View: West

Description of View: Sloping trench sidewalls between JB-2 and JB-3



Photograph No.: 60

Date: 8/20/13

Location: JB-3

Direction of View: Southwest

Description of View: Excavating footprint of JB-3

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 59 & 60
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 61

Date: 8/22/13

Location: JB-3

Direction of View: North

Description of View: View of temporary sumps installed for groundwater control



Photograph No.: 62

Date: 9/9/13

Location: JB-3

Direction of View: West

Description of View: Forming sidewalls of JB-3

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 61 & 62
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 63
Date: 9/10/13
Location: JB-3
Direction of View: North
Description of View: Pouring concrete sidewalls of JB-3



Photograph No.: 64
Date: 11/1/13
Location: JB-3
Direction of View: West
Description of View: View of frame anchors

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 63 & 64
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 65

Date: 11/5/13

Location: JB-3

Direction of View: Northeast

Description of View: Concrete testing performed by McCallum Testing Inc.



Photograph No.: 66

Date: 11/5/13

Location: JB-3

Direction of View: Northeast

Description of View: Float finishing top of JB-3

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 65 & 66
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 67

Date: 10/8/13

Location: JB-3

Direction of View: West

Description of View: Liner installation activities performed by Plastic Fusion Fabricators, Inc.



Photograph No.: 68

Date: 10/16/13

Location: JB-3

Direction of View: Southwest

Description of View: Installation of pipe boot west of JB-3

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 67 & 68
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 69
Date: 9/14/13
Location: JB-3 to JB-4
Direction of View: West
Description of View: Compaction testing on select fill material



Photograph No.: 70
Date: 10/15/13
Location: JB-3 to JB-4
Direction of View: West
Description of View: Destructive liner seam sample location between JB-3 and JB-4

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 69 & 70
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 71

Date: 10/22/13

Location: JB-3 to JB-4

Direction of View: Northwest

Description of View: Installation of dual 36-inch RCP between JB-3 and JB-4



Photograph No.: 72

Date: 8/1/13

Location: JB-4

Direction of View: West


Description of View: Excavating footprint of JB-4

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 71 & 72
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 73

Date: 8/16/13

Location: JB-4

Direction of View: East

Description of View: Forming foundation of JB-4



Photograph No.: 74

Date: 8/22/13

Location: JB-4

Direction of View: South

Description of View: Forming sidewalls of JB-4



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRS COMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

WRScompass Project No. 33-74-120000

SITE PHOTOGRAPHS 73 & 74
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 75
Date: 9/5/13
Location: JB-4
Direction of View: East
Description of View: Walls and foundation of JB-4



Photograph No.: 76
Date: 11/5/13
Location: JB-4
Direction of View: Northeast
Description of View: Pouring concrete top of JB-4

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 75 & 76
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 77

Date: 10/18/13

Location: JB-4 to Curb Inlet

Direction of View: South

Description of View: Installation of 24-inch RCP between JB-4 and Curb Inlet



Photograph No.: 78

Date: 3/8/13

Location: Existing Curb Inlet on the east side of Veneer Road

Direction of View: East

Description of View: Existing Curb Inlet prior to replacement

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 77 & 78
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 79

Date: 10/17/13

Location: East side of Veneer Road

Direction of View: North

Description of View: Installation of replacement pre-cast Curb Inlet



Photograph No.: 80

Date: 8/22/13

Location: Elm Avenue

Direction of View: West

Description of View: Excavating trench for sewer and water main installations on Elm Avenue



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRS COMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

WRScompass Project No. 33-74-120000

SITE PHOTOGRAPHS 79 & 80
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 81

Date: 8/23/13

Location: Veneer Road

Direction of View: South

Description of View: Excavating trench for sewer and water main installations on Veneer Road



Photograph No.: 82

Date: 8/16/13

Location: Veneer Road

Direction of View: South

Description of View: Load-out of contaminated soils

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 81 & 82
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 83

Date: 8/16/13

Location: Veneer Road

Direction of View: East

Description of View: Close up view of contaminated soils removed during utility relocation activities



Photograph No.: 84

Date: 9/18/13

Location: Veneer Road

Direction of View: N/A

Description of View: Product observed at the bottom of trench during excavation activities

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 83 & 84
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 85

Date: 8/24/13

Location: Elm Avenue

Direction of View: Southwest

Description of View: Installation of new sewer main with steel casing



Photograph No.: 86

Date: 9/19/13

Location: Veneer Road

Direction of View: South

Description of View: Installation of new sewer main with steel casing

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 85 & 86
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07




Photograph No.: 87

Date: 9/19/13

Location: Veneer Road

Direction of View: South

Description of View: Installation of both the sewer and water mains



Photograph No.: 88

Date: 9/18/13

Location: Elm Avenue

Direction of View: Northwest


Description of View: Fusing HDPE pipe connections

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 87 & 88
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 89
Date: 8/20/13
Location: Veneer Road
Direction of View: North
Description of View: Installation of new valves



Photograph No.: 90
Date: 8/23/13
Location: Elm Avenue
Direction of View: West
Description of View: Installation of pipe restraints

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 89 & 90
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 91

Date: 8/25/13

Location: Elm Avenue

Direction of View: East

Description of View: Backfilling and compacting select fill material above the sewer and water mains



Photograph No.: 92

Date: 9/30/13

Location: Veneer Road

Direction of View: South

Description of View: Backfilling and compacting select fill material above the sewer and water mains

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 91 & 92
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 93

Date: 11/1/13

Location: Elm Avenue

Direction of View: West

Description of View: Backfilling with VDOT 21A road base material



Photograph No.: 94

Date: 11/10/13

Location: Elm Avenue and Veneer Road

Direction of View: West

Description of View: Preparing roadway sub-base for asphalt

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 93 & 94
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 95

Date: 11/12/13

Location: Veneer Road

Direction of View: West

Description of View: Virginia Paving applies VDOT BM-25.0 base course asphalt



Photograph No.: 96

Date: 11/14/13

Location: Veneer Road

Direction of View: Southwest

Description of View: Compacting SM-9.5A surface course asphalt

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 95 & 96
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 97

Date: 11/6/13

Location: Elm Avenue

Direction of View: East

Description of View: Bissette Construction installs concrete curb and gutter along the north side of Elm Ave.



Photograph No.: 98

Date: 11/18/13

Location: Elm Avenue

Direction of View: Southwest

Description of View: Bissette Construction installs concrete sidewalk along the north side of Elm Ave.

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 97 & 98
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07




Photograph No.: 99

Date: 7/23/13

Location: Groundwater Collection Trench

Direction of View: Northwest

Description of View: Construction of the Groundwater Collection Trench



Photograph No.: 100

Date: 7/19/13

Location: Groundwater Collection Trench

Direction of View: South

Description of View: Backfilling and compacting trench with select fill material

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 99 & 100
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 101

Date: 7/19/13

Location: Groundwater Collection Trench

Direction of View: Southwest

Description of View: View of compaction testing performed on select fill material



Photograph No.: 102

Date: 9/25/13

Location: Decontamination Pad

Direction of View: North

Description of View: View of decontamination pad utilized for cleaning contaminated equipment

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 101 & 102
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 103

Date: 10/31/13

Location: Frac Tank

Direction of View: North

Description of View: View of Frac Tank decontamination activities performed in Level B PPE



Photograph No.: 104

Date: 4/2/13

Location: Water Treatment System

Direction of View: North


Description of View: View of water treatment system

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 103 & 104
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 105

Date: 7/25/13

Location: Treatment Trailer

Direction of View: South

Description of View: Minor spill cleanup inside treatment trailer



Photograph No.: 106

Date: 7/25/13

Location: Outside Treatment Trailer

Direction of View: East

Description of View: View of WRScompass personnel containing spill outside treatment trailer with clean sand.

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 105 & 106
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 107

Date: 11/5/13

Location: Weir Box

Direction of View: Northeast

Description of View: Minor spill cleanup around weir box caused by hose failure



Photograph No.: 108

Date: 11/17/13

Location: Stockpile-A

Direction of View: West

Description of View: View of Stockpile-A staging area

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 107 & 108
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 109
Date: 11/17/13
Location: Stockpile-A
Direction of View: Southwest
Description of View: Another view of Stockpile-A



Photograph No.: 110
Date: 11/17/13
Location: Stockpile-A
Direction of View: East
Description of View: Super-sacks containing contaminated PPE and absorbant pads were staged at Stockpile-A

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 109 & 110
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 111

Date: 9/10/13

Location: Dixon Property

Direction of View: Southwest

Description of View: View of temporary bypass road construction utilizing rip rap material for sub-base



Photograph No.: 112

Date: 9/10/13

Location: Dixon Property

Direction of View: Southwest

Description of View: Continuing with temporary bypass road construction

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 111 & 112
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07




Photograph No.: 113

Date: 9/12/13

Location: Dixon Property

Direction of View: Northeast

Description of View: View of temporary bypass road completed and open to traffic



Photograph No.: 114

Date: 4/9/13

Location: Top of Jordan Bridge

Direction of View: Southwest


Description of View: Aerial site view during construction activities

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 113 & 114
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 115
Date: 4/26/13
Location: Top of Jordan Bridge
Direction of View: South
Description of View: Aerial site view during backfilling activities



Photograph No.: 116
Date: 11/16/13
Location: North side of Elm Avenue
Direction of View: East
Description of View: View of straw matting applied to seeded/fertilized areas to prevent erosion

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 115 & 116
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 117

Date: 11/16/13

Location: South side of Elm Avenue

Direction of View: West

Description of View: View of straw bales placed around JB-3 to prevent erosion



Photograph No.: 118

Date: 11/20/13

Location: East side of site

Direction of View: Southwest

Description of View: Final site grading activities

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 117 & 118
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 119
Date: 11/24/13
Location: Veneer Road
Direction of View: North
Description of View: View of Veneer Road (Post-construction)




Photograph No.: 120
Date: 11/24/13
Location: South side of Elm Avenue
Direction of View: West
Description of View: View of Elm Avenue (Post-construction)

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 119 & 120
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 121

Date: 11/24/13

Location: AWI project site

Direction of View: South

Description of View: Site view looking to the South (Post-construction)



Photograph No.: 122

Date: 11/24/13

Location: AWI project site

Direction of View: East

Description of View: Site view looking to the East (Post-construction)

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 121 & 122
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 123

Date: 11/24/13

Location: AWI project site (Southwest corner)

Direction of View: East

Description of View: Site view looking to the East (Post-construction)



Photograph No.: 124

Date: 11/24/13

Location: AWI project site

Direction of View: North


Description of View: Site view looking to the North (Post-construction)

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 123 & 124
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07



Photograph No.: 125
Date: 11/24/13
Location: JB-1
Direction of View: North
Description of View: View of JB-1 (Post-construction)



Photograph No.: 126
Date: 11/24/13
Location: AWI project site (Northeast corner)
Direction of View: West
Description of View: Site view looking to the West (Post-construction)

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 125 & 126
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 127
Date: 11/24/13
Location: JB-2
Direction of View: Northwest
Description of View: View of JB-2 (Post-construction)



Photograph No.: 128
Date: 11/16/13
Location: JB-3
Direction of View: West
Description of View: View of JB-3 (Post-construction)

WRSScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRSSCOMPASS
 221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
 PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 127 & 128
 ELM AVENUE STORM DRAIN RELOCATION AND
 GROUNDWATER COLLECTION TRENCH
 ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
 PORTSMOUTH, VIRGINIA
 EPA CONTRACT No. EP-S3-07-07



Photograph No.: 129

Date: 12/18/13

Location: JB-4

Direction of View: Northwest

Description of View: View of JB-4 (Post-construction)



Photograph No.: 130

Date: 12/19/13

Location: Southside of Elm Avenue

Direction of View: East

Description of View: Restoration along the South side of Elm Avenue (Post-construction)

WRScompass Project No. 33-74-120000



WRS INFRASTRUCTURE & ENVIRONMENT, INC., D/B/A WRScompass
221 HOBBS STREET, SUITE 108, TAMPA, FLORIDA 33619
PH: (813) 684-4400 FAX: (813) 684-9177

SITE PHOTOGRAPHS 129 & 130
ELM AVENUE STORM DRAIN RELOCATION AND
GROUNDWATER COLLECTION TRENCH
ATLANTIC WOOD INDUSTRIES (AWI) SUPERFUND SITE
PORTSMOUTH, VIRGINIA
EPA CONTRACT No. EP-S3-07-07